



Lower Perennial Stream



Intermittent Stream





Jim Moore Road-Sharon Church 230 kV Transmission Line and Flanagan Mill Road Advanced Land Purchase Substation Site Gwinnett and Barrow Counties, Georgia

Representative Photographs of Jurisdictional Streams

Date: January 2008
Scale: Not Applicable
Project No.: 04123204

Figure 7



APPENDIX A Agency Coordination

Protected Species Correspondence Summary

In addition to reviewing existing database information, a letter requesting any additional protected species information for the proposed project area was sent to the GADNR-NCS on August 8, 2007 (attached). A response was received on September 11, 2007. Please refer to the attached correspondence.

The tentative list of known protected species was compiled by review of the federal "Redbook" – Region 4, a copy of the United States Fish and Wildlife Service (USFWS) county database (WordPerfect 6.1 tables updated December 2006) http://www.fws.gov/athens/endangered/counties_endangered.html, Protected Animals of Georgia (GDNR, 1999), Protected Plants of Georgia (Patrick et al., 1995), and review of element occurrence records on the Georgia Department of Natural Resources Non-game Conservation Service (GADNR-NCS) web site http://www.dnr.state.ga.us/dnr/wild/.

Noel Holcomb, Commissioner Dan Forster, Director

Georgia Department of Natural Resources Wildlife Resources Division

Nongame Conservation Section 2065 U.S. Highway 278, S.E., Social Circle, Georgia 30025-4743 (770) 918 6411

September 11, 2007

Kevin Mullinax Ecologist Jordan, Jones, & Goulding 6801 Governors Lake Parkway Building 200 Norcross, GA 30071

Subject:

Known Occurrences of Conservation Areas and Special Concern Animals and Plants On or Near Jim Moore Road - Sharon Church 230 kV Transmission Line Project, Barrow County, Georgia

Dear Mr. Mullinax:

This is in response to your request of August 8, 2007. According to our records, within a three-mile radius of the project corridor there are the following Natural Heritage Database occurrences:

Jim Moore Road Substation (-83.90664, 34.03491; NAD27):

Aesculus glabra (Ohio Buckeye) approx. 1.5 mi. NE of site
Alcovy River [High Priority Stream] approx. 2.0 mi. SW of site
Apalachee River [High Priority Stream] approx. 1.0 mi. SW of site
Little Mulberry River Park [Gwinnett County Parks and Recreation Department] approx.
0.5 mi. E of site

Gwinnett / Barrow County Line (-83.85428, 34.03837; NAD27):

Panax quinquefolius (American Ginseng) approx. 1.5 mi. NW of site

GA Veratrum woodii (Ozark Bunchflower) approx. 1.5 mi. NW of site

Sharon Church Substation (-83.80850, 34.09456; NAD27):

- US Amphianthus pusillus (Pool Sprite) approx. 2.5 mi. N of site
- GA Cyprinella xaenura (Altamaha Shiner) approx. 1.0 mi. NW of site in Duncan Creek Hemidactylium scutatum (Four-toed Salamander) approx. 2.0 mi. N of site
- US Isoetes melanospora (Black-spored Quillwort) approx. 2.5 mi. N of site
- US Isoetes tegetiformans (Mat-forming Quillwort) approx. 2.5 mi. N of site
- * Entries above proceeded by "US" indicates species with federal status in Georgia (Protected or Candidate). Species that are federally protected in Georgia are also state protected; "GA" indicates Georgia protected species.

Recommendations:

We have no records of species of concern within the project corridor. However, three federally listed species, *Amphianthus pusillus* (Pool Sprite), *Isoetes melanospora* (Black-spored Quillwort) and *Isoetes tegetiformans* (Mat-forming Quillwort) are within three miles of the proposed project. These species rely on granite rock outcrop habitats. If no outcrop habitats are found within the project corridor, this project should not negatively impact these species. We recommend thoroughly surveying the project corridor for these and other species of concern before any work is begun. Section 9 of the Endangered Species Act states that taking or harming of a listed species is prohibited. We recommend all requestors with projects located near federally protected species consult with Robin Goodloe of the United States Fish and Wildlife Service (706-613-9493, ext.221 or Robin_Goodloe@fws.gov).

In order to protect aquatic habitats and water quality, we recommend that all machinery be kept out of creeks during powerline construction. Streams should not be culverted/forded to allow equipment access during construction or for future ROW maintenance. Further, we strongly advocate retaining at least a 25-foot vegetative buffer between each stream bank and the closest power pole, and allow this buffer to regenerate to shrub-scrub growth after the pipe is installed (if the landowner is willing). We realize that some trees may have to be removed, but recommend that shrubs and ground vegetation be left in place. Wider buffers may be needed for projects where land slopes sharply toward the stream being crossed. We also recommend that stringent erosion control practices be used during construction activities and that vegetation is reestablished on disturbed areas as quickly as possible. Silt fences and other erosion control devices should be inspected and maintained until soil is stabilized by vegetation. Please use natural vegetation and grading techniques (e.g. vegetated swales, turn-offs, vegetated buffer strips) that will ensure that the project area does not serve as a conduit for storm water or pollutants into the water during or after construction. These measures will help protect water quality in the vicinity of the project as well as in downstream areas.

Please be aware that this project occurs near the Alcovy and Apalachee Rivers, both high priority streams. As part of an effort to develop a comprehensive wildlife conservation strategy for the state of Georgia, the Wildlife Resources division has developed and mapped a list of streams that are important to the protection or restoration of rare aquatic species and aquatic communities. High priority waters and their surrounding watersheds are a high priority for a broad array of conservation activities, but do not receive any additional legal protections. We now have GIS ESRI shapefiles of GA high priority waters available on our website (http://www.georgiawildlife.com/content/displaycontent.asp?txtDocument=89&txtPage=13). Please contact the Georgia Natural Heritage Program if you would like additional information on high priority waters.

New Data Available on the Nongame Conservation Section Website

We have recently updated the Nongame Conservation Section Website!!! You can view the updated rare species and natural community information by Quarter Quad, County and HUC8 Watershed. To access this information, please visit our GA Rare Species and Natural Community Information page at:

http://georgiawildlife.dnr.state.ga.us/content/displaycontent.asp?txtDocument=89

An updated ESRI shape file of our rare species and natural community data by quarter quad and county is also available. It can be downloaded from: http://georgiawildlife.dnr.state.ga.us/assets/documents/gnhp/gnhpds.zip

Disclaimer:

Please keep in mind the limitations of our database. The data collected by the Nongame Conservation Section comes from a variety of sources, including museum and herbarium records, literature, and reports from individuals and organizations, as well as field surveys by our staff biologists. In most cases the information is not the result of a recent on-site survey by our staff. Many areas of Georgia have never been surveyed thoroughly. Therefore, the Nongame Conservation Section can only occasionally provide definitive information on the presence or absence of rare species on a given site. Our files are updated constantly as new information is received. Thus, information provided by our program represents the existing data in our files at the time of the request and should not be considered a final statement on the species or area under consideration.

If you know of populations of special concern species that are not in our database, please fill out the appropriate data collection form and send it to our office. Forms can be obtained through our web site (http://www.georgiawildlife.com) or by contacting our office. If I can be of further assistance, please let me know.

Sincerely,

Katrina Morris

Thina Moris

Environmental Review Coordinator



APPENDIX B Wetland Data Sheets

Data Form

Routine Wetland Determination

Job Number: 04123215
Town/Village/City:

Wetland Data Point: J Wet 1

Project/Site: Jim Moore Road-Sharon Church Transmission Line Applicant/Owner: Georgia Transmission Corporation Investigator: KAM				Date: J	Date: July 16, 2007 County: Gwinnett and Barrow			
				County:				
				State: Georgia				
[True] Do norm	nal circumstances exi	ist on the site?		Commu	nity ID: PEM1B			
[False] Is the site significantly disturbed (Atypical Situation)?				Station I	ID:			
[False] Is the area a potential problem area?				Plot ID:				
/egetation								
Dominant	Species		Common Name / Co	fC	% Cover	Indicator		
Herbaceous								
X	Juncus effusus		Rush,Soft			FACW+		
X X	Eleocharis obtusa		Spikerush,Blunt Willow,Primrose			OBL OBL		
X	Ludwigia decurrens Carex intumescens		Sedge,Bladder			FACW		
		FAC (except FAC-):	MATERIA DE LA CONTRACTOR DEL CONTRACTOR DE LA CONTRACTOR	Cowardin Cla	ssification:	17011		
Remarks	, , , , , , , , , , , , , , , , , , , ,	Visit Programme						
lydrology		9	Primary Wetland Hydrology Ii	ndicators	Secondary Hydrology I	ndicators		
[] Recorded	l Data (describe in re		[] Inundated		Oxidized root channels			
Carlo 18 December 2015 Person	ream, Lake, or Tide (ANADATA USPARA	[X] Saturated in upper 12	inches	[] Water-stained leaves			
B 50	rial Photograph	75 0	[] Water marks		[] Local soil survey data			
R Raine	her (describe in rema	ırks)	[] Drift lines		[] FAC-Neutral test			
		···/	Sediment deposits		Other (explain in remarks)			
Field Observa	ations:		[X] Drainage patterns in w	etlande	[] Other (explain ii	i remarks)		
Depth	of Surface Water(in.):	[X] Diamage patterns in w	cualius				
Depth	to Free Water in Pit(in.):						
	to Saturated Soils(in	.):						
Depth	to Saturated Soils(in	.):						
	to Saturated Soils(in	.):						
Depth	to Saturated Soils(in	.):						
Depth Remarks		Mottle / 2nd Mottl	le	Texture,				
Depth Remarks Soils Depth Hor. (in.)	. Matrix Color		le Abundance Contrast	Structure, et	с.			
Depth Remarks Soils Depth Hor	. Matrix	Mottle / 2nd Mottl			с.			
Depth Remarks Foils Depth Hor (in.) 0-12	Matrix Color 10YR 4/1	Mottle / 2nd Mottl		Structure, et	с.			
Depth Remarks Foils Depth Hor (in.) 0-12 Hydric Soils I	: Matrix Color 10YR 4/1	Mottle / 2nd Mottl	Abundance Contrast	Structure, et Clay Loam	с.			
Depth Remarks oils Depth Hor. (in.) 0-12 Hydric Soils I [] Histos	: Matrix Color 10YR 4/1	Mottle / 2nd Mottl	Abundance Contrast [] Concretions	Structure, et Clay Loam				
Depth Remarks Foils Depth Hor. (in.) 0-12 Hydric Soils I [] Histos [] Histic	: Matrix Color 10YR 4/1 Indicators sol Epipedon	Mottle / 2nd Mottl	Abundance Contrast [] Concretions [] High Organi	Structure, et Clay Loam c % in Surface Layer	in Sandy Soils			
Depth Remarks Foils Depth Hor. (in.) 0-12 Hydric Soils I [] Histos [] Histic [] Sulfidi	: Matrix Color 10YR 4/1 Indicators col Epipedon ic Odor	Mottle / 2nd Mottl Color	Abundance Contrast [] Concretions [] High Organi [] Organic Stre	Structure, et Clay Loam c % in Surface Layer eaking in Sandy Soils	in Sandy Soils			
Depth Remarks Soils Depth Hor. (in.) 0-12 Hydric Soils I [] Histos [] Histic [] Sulfidi [] Probal	: Matrix Color 10YR 4/1 Indicators sol Epipedon ic Odor ble Aquatic Moist Re	Mottle / 2nd Mottl Color	Abundance Contrast [] Concretions [] High Organi [] Organic Stre [] Listed on Lo	Structure, et Clay Loam c % in Surface Layer eaking in Sandy Soils cal Hydric Soils List	in Sandy Soils			
Depth Remarks Soils Depth Hore (in.) 0-12 Hydric Soils I [] Histos [] Histic [] Sulfidi [] Probal [X] Reduct	: Matrix Color 10YR 4/1 Indicators sol Epipedon ic Odor ble Aquatic Moist Re	Mottle / 2nd Mottl Color	Abundance Contrast [] Concretions [] High Organi [] Organic Stre [] Listed on Lo [] Listed on Na	Structure, et Clay Loam c % in Surface Layer eaking in Sandy Soils cal Hydric Soils List ttional Hydric Soils List	in Sandy Soils			
Depth Remarks Soils Depth Hore (in.) 0-12 Hydric Soils I [] Histos [] Histic [] Sulfidi [] Probal [X] Reduct	: Matrix Color 10YR 4/1 Indicators sol Epipedon ic Odor ble Aquatic Moist Re	Mottle / 2nd Mottl Color	Abundance Contrast [] Concretions [] High Organi [] Organic Stre [] Listed on Lo	Structure, et Clay Loam c % in Surface Layer eaking in Sandy Soils cal Hydric Soils List ttional Hydric Soils List	in Sandy Soils			
Depth Remarks Soils Depth Hor. (in.) 0-12 Hydric Soils I [] Histos [] Histic [] Sulfidi [] Probal [X] Reduct	: Matrix Color 10YR 4/1 Indicators sol Epipedon ic Odor ble Aquatic Moist Re	Mottle / 2nd Mottl Color	Abundance Contrast [] Concretions [] High Organi [] Organic Stre [] Listed on Lo [] Listed on Na	Structure, et Clay Loam c % in Surface Layer eaking in Sandy Soils cal Hydric Soils List ttional Hydric Soils List	in Sandy Soils			
Depth Remarks Soils Depth Hor (in.) 0-12 Hydric Soils I [] Histos [] Histic [] Sulfidi [] Probal [X] Reduc [X] Gleyer	Matrix Color 10YR 4/1 Indicators sol Epipedon ic Odor ble Aquatic Moist Re sing Conditions d or Low-Chroma Co	Mottle / 2nd Mottl Color	Abundance Contrast [] Concretions [] High Organi [] Organic Stre [] Listed on Lo [] Listed on Na [] Other (expla	Structure, et Clay Loam c % in Surface Layer eaking in Sandy Soils cal Hydric Soils List ational Hydric Soils List in in remarks)	in Sandy Soils			
Depth Remarks Depth Hor. (in.) 0-12 Hydric Soils I [] Histos [] Histic [] Sulfidi [] Probal [X] Reduc [X] Gleyed Unit Name:	Matrix Color 10YR 4/1 Indicators sol Epipedon ic Odor ble Aquatic Moist Re sing Conditions d or Low-Chroma Co	Mottle / 2nd Mottl Color	Abundance Contrast [] Concretions [] High Organi [] Organic Stre [] Listed on Lo [] Listed on Na [] Other (expla	Structure, et Clay Loam c % in Surface Layer eaking in Sandy Soils cal Hydric Soils List ational Hydric Soils List in in remarks)	in Sandy Soils			
Depth Remarks Depth Hor. (in.) 0-12 Hydric Soils I [] Histos [] Histo [] Sulfidi [] Probal [X] Reduc [X] Gleyer Unit Name: Drainage Clar Remarks	. Matrix Color 10YR 4/1 Indicators sol Epipedon ic Odor ble Aquatic Moist Re sing Conditions d or Low-Chroma Co	Mottle / 2nd Mottl Color	Abundance Contrast [] Concretions [] High Organi [] Organic Stre [] Listed on Lo [] Listed on Na [] Other (expla	Structure, et Clay Loam c % in Surface Layer eaking in Sandy Soils cal Hydric Soils List ational Hydric Soils List in in remarks)	in Sandy Soils			
Depth Remarks Soils Depth Hor (in.) 0-12 Hydric Soils I [] Histos [] Histic [] Sulfidi [] Probal [X] Reduc [X] Gleyer Unit Name: Drainage Cla Remarks	: Matrix Color 10YR 4/1 Indicators sol Epipedon ic Odor ble Aquatic Moist Re sing Conditions d or Low-Chroma Co	Mottle / 2nd Mottl Color	Abundance Contrast [] Concretions [] High Organi [] Organic Stre [] Listed on Lo [] Listed on Na [] Other (explation of the control of	Structure, et Clay Loam c % in Surface Layer eaking in Sandy Soils cal Hydric Soils List ational Hydric Soils Lis in in remarks) ons match map	in Sandy Soils			
Depth Remarks Soils Depth Hor (in.) 0-12 Hydric Soils I [] Histos [] Histic [] Sulfidi [] Probal [X] Reduc [X] Gleyer Unit Name: Drainage Cla Remarks Vetland De [True] Hydrop	Matrix Color 10YR 4/1 Indicators col Epipedon ic Odor ble Aquatic Moist Re cing Conditions d or Low-Chroma Co ss: termination phytic Vegetation Pre	Mottle / 2nd Mottl Color	Abundance Contrast [] Concretions [] High Organi [] Organic Stre [] Listed on Lo [] Listed on Na [] Other (explation of the control of	Structure, et Clay Loam c % in Surface Layer eaking in Sandy Soils cal Hydric Soils List ational Hydric Soils List in in remarks)	in Sandy Soils			
Depth Remarks Soils Depth Hor (in.) 0-12 Hydric Soils I [] Histos [] Histic [] Sulfidi [] Probal [X] Reduc [X] Gleyer Unit Name: Drainage Clar Remarks Vetland De [True] Hydrog [True] Hydric	Matrix Color 10YR 4/1 Indicators col Epipedon ic Odor ble Aquatic Moist Re cing Conditions d or Low-Chroma Co ss: termination ohytic Vegetation Pre Soils Present	Mottle / 2nd Mottl Color gime olors	Abundance Contrast [] Concretions [] High Organi [] Organic Stre [] Listed on Lo [] Listed on Na [] Other (explation of the control of	Structure, et Clay Loam c % in Surface Layer eaking in Sandy Soils cal Hydric Soils List ational Hydric Soils Lis in in remarks) ons match map	in Sandy Soils			
Depth Remarks Soils Depth Hor (in.) 0-12 Hydric Soils I [] Histos [] Histic [] Sulfidi [] Probal [X] Reduc [X] Gleyer Unit Name: Drainage Clar Remarks Vetland De [True] Hydror [True] Hydric	Matrix Color 10YR 4/1 Indicators col Epipedon ic Odor ble Aquatic Moist Re cing Conditions d or Low-Chroma Co ss: termination phytic Vegetation Pre	Mottle / 2nd Mottl Color gime olors	Abundance Contrast [] Concretions [] High Organi [] Organic Stre [] Listed on Lo [] Listed on Na [] Other (explation of the control of	Structure, et Clay Loam c % in Surface Layer eaking in Sandy Soils cal Hydric Soils List ational Hydric Soils Lis in in remarks) ons match map	in Sandy Soils			

Data Form Routine Wetland Determination

Job Number: 04123215 Town/Village/City:

Wetland Data Point: J Wet 2

Project/Site: Jim Moore Road-Sharon Church Transmission Line				Date: July 16, 2007			
Applicant/Owner: Georgia Transmission Corporation				County: Gwinnett and Barrow			
Investigator: 1	KAM				State: Ge	orgia	
[True] Do nor	mal circumstances exi	st on the site?			Communit	y ID: PEM1B	=======================================
[False] is the	site significantly distur	bed (Atypical Situatior	1)?		Station ID		
[False] is the	area a potential proble	em area?			Plot ID:		
Vegetation							
Dominant	Species		Comm	on Name / CofC		% Cover	Indicator
<u>Herbaceous</u>							
X	Juncus effusus		Rush,				FACW+
X	Scirpus cyperinus	- 1722	Wool-				OBL
X X	Polygonum sagittatu Typha latifolia	ım		umb,Arrow-Leaf .Broad-Leaf			OBL OBL
x	Ludwigia decurrens			,Broad-Lear ,Primrose			OBL
x	Carex intumescens			,Bladder			FACW
	at are OBL, FACW, or	FAC (except FAC-):		*	Cowardin Class	sification:	
Remarks							
Hydrology		<u></u>	Primary Wetla	nd Hydrology Indicato	ers S	econdary Hydrology I.	ndicators
5 35	d Data (describe in re		[] Inundat		⁴⁶ 52	[X] Oxidized root ch	
Carlotte Control of the Control of t	tream, Lake, or Tide G	7.0 (E. 1902)		ed ed in upper 12 inches		[] Water-stained le	
B 16	erial Photograph	Dage	10 Barrier 10	500		151 (F a	
R A.C.		1	[] Water n			[] Local soil survey [] FAC-Neutral tes	
[]0	[] Other (describe in remarks)						
Field Observ	vations:		[] Sediment deposits			[] Other (explain in remarks)	
Depth	n of Surface Water(in.)):	[X] Drainag	e patterns in wetland	S		
	n to Free Water in Pit(i						
	n to Saturated Soils(in.						
Remarks Soils							
Depth Ho	or. Matrix	Mottle / 2nd Mottle	9		Texture,		
(in.)	Color	Color	Abundance	Contrast	Structure, etc.		
0-12	10YR 4/1				Clay Loam		
Hydric Soils	Indicators						
[]Histo	sol		1] Concretions			
[]Histic	: Epipedon]] High Organic % in	Surface Layer in	Sandy Soils	
[] Sulfic	dic Odor		I] Organic Streaking	in Sandy Soils		
[] Prob	able Aquatic Moist Re	gime	Ť] Listed on Local Hy	dria Saile Liet		
					ulic Solis List		
	icing Conditions			Listed on National			
[X] Redu		lors	I		Hydric Soils List		
[X] Redu	icing Conditions	lors]] Listed on National	Hydric Soils List		
[X] Redu [X] Gley	ucing Conditions ed or Low-Chroma Co	lors]] Taxo] Listed on National] Other (explain in re	Hydric Soils List emarks)		
[X] Redu [X] Gleye Unit Name:	ucing Conditions ed or Low-Chroma Co	lors]] Taxo] Listed on National] Other (explain in re nomy:	Hydric Soils List emarks)		
[X] Redu [X] Gleyo Unit Name: Drainage Cli Remarks	ucing Conditions ed or Low-Chroma Co	lors]] Taxo] Listed on National] Other (explain in re nomy:	Hydric Soils List emarks)		
[X] Redu [X] Gleyo Unit Name: Drainage Cli Remarks Wetland De [True] Hydro [True] Hydro	icing Conditions ed or Low-Chroma Co ass:	sent	[] Taxc] [] Listed on National] Other (explain in re nomy:	Hydric Soils List emarks) utch map		

Data Form Routine Wetland Determination

Job Number: **04123215** Town/Village/City:

Wetland Data Point: Upland 1

						A to come with the second control of \$100 and \$1			
Project/Site: Jim Moore Road-Sharon Church Transmission Line				Date:	Date: July 16, 2007				
Applicant/Owner: Georgia Transmission Corporation					County: Gwinnett and Barrow				
Investigator: KAM					State: Georgia				
[True] Do normal circumstances exist on the site?				1,40,403,00,000	Community ID: Upland				
171. v 171. v 181. v			n)2			100 APR P	ariu.		
[False] Is the site significantly disturbed (Atypical Situation)? [False] Is the area a potential problem area?						Station ID: Plot ID: for J Wet 1			
		alea:			FIOLIL	J. IOI S WELL			
Vegetation									
Dominant	Species		Comn	non Name / CofC			% Cover	Indicator	
<u>Herbaceous</u>		7808000		• • • • • • • • • • • • • • • • • • •				=	
X	Polystichum acrosticho	ides	Fern,C	hristmas				FAC	
<u>Tree</u> X	Pinus taeda		Pine I	oblolly				FAC	
x	Cornus florida			ood,Flowering				FACU	
Х	Carya glabra			y,Sweet Pignut				FACU	
Х	Fagus grandifolia		Beech	,American				FACU	
Х	Quercus falcata		Oak,S	outhem Red				FACU-	
<u>Vine</u>	2 1 2 12 1		_	er ex				F40	
X % Chasing the	Smilax rotundifolia	C (event EAC)	2000A10	brier,Common	Causerdie (Nassifiaation		FAC	
==02 A7	at are OBL, FACW, or FA	(except FAC-):	42		Cowardin	Classification:			
Remarks									
Hydrology		8)	Primary Wetla.	nd Hydrology Indica	ators	Secondary	Hvdrology I	Indicators	
[]Recorde	d Data (describe in rema		[] Inundat	errana -					
NEW PERIOD AND AND AND AND AND AND AND AND AND AN	tream, Lake, or Tide Gag	No procedu	· · · · · · · · · · · · · · · · · · ·	ed in upper 12 inch	ec	[] Oxidized root channel [] Water-stained leaves			
A Bloom	erial Photograph	er.	[] Water n		C3	See See an account			
R B		Ň	A State and a			[] Local soil survey data			
[]0	ther (describe in remarks	9)	[] Drift line			[] FAC-Neutral test			
Field Observ	/ations:		[] Sedime		ross • 000	[] Other (explain in remarks)			
Depth	of Surface Water(in.):		[] Drainag	je patterns in wetlar	n wetlands				
and the	to Free Water in Pit(in.):	:							
Section 1	to Saturated Soils(in.):								
2011									
Remarks									
No hydrolo	gy observed.								
Soils									
Depth Ho	r. Matrix	Mottle / 2nd Mottl	la.		Texture,				
(in.)	Color	Color	Abundance	Contrast	Structure,	etc			
0-12	10YR 4/6	00101	Abundance	Contrast	Clay Loam				
- IL	10111 20				Olay Loan	<i>i</i> i			
Hydric Soils	Indicators								
Table 1 Account to the Control of th			· r	1 Congretions					
4				Concretions					
[] Histic Epipedon			[] High Organic % in Surface Layer in Sandy Soils						
[] Sulfidic Odor			[] Organic Streaking in Sandy Soils						
[] Probable Aquatic Moist Regime			[] Listed on Local Hydric Soils List						
[] Reducing Conditions			[] Listed on National Hydric Soils List						
[] Gleyed or Low-Chroma Colors			[] Other (explain in remarks)						
Unit Name:			Tax	n 0 m) ("					
				onomy:	2070				
Drainage Cl	ass:		F FF	Field Observations i	matcn map				
Remarks									
Wetland De	etermination								
[False] Hydr	ophytic Vegetation Prese	ent	ri	False] This Data Po	nint is a Wetlan	d			
	an Francisco and an and an and an and an an and an an and an an an and an	ATT.	ŗ.	uisej illis Data Fu	ZIIIC IS A VVCIIAIII	ч			
	ic Soils Present								
GER TOURSENESS CHARLE	and Hydrology Present								
Remarks									

Data Form

Routine Wetland Determination

Job Number: 04123215 Town/Village/City:

Wetland Data Point: Upland 2

Project/S	ite: Jim Moore Road-Sha	ron Church Transmissior	Line	Date: July 16, 2007			
Applicant/Owner: Georgia Transmission Corporation				County: Gwinnett and Barrow			
Investiga	tor: KAM			State: Georgia			
[True] Do	normal circumstances exi	st on the site?		Community ID: Upland	=======================================		
[False] Is the site significantly disturbed (Atypical Situation)?				Station ID:			
[False] Is the area a potential problem area?				Plot ID: for J Wet 2			
Vegetat	n May 200 Marigh No. 4004 (AA No. 2006) An earl # arour 200 anns Ar 200 Anns an an 10 # ar Ar Anns an 10 Anns a An 200	230-0-0(4 Append 20 - 3		- A STATE PARTY TO WAR DESCRIPTION OF THE PARTY.			
Dominar			Common Name / CofC	% Cover	Indicator		
Herbace			Common Name / Corc	% Cover	iliuicatoi		
X	Andropogon virginic	us	Broom-Sedge		FAC-		
X	Eupatorium capillifo		Thorough-Wort,Small Dog-Fenr	nel	FACU		
Х	Rubus argutus		Blackberry,Serrate-Leaf		FACU+		
<u>Shrub</u>							
X	Liriodendron tulipife		Tree,Tulip		FAC		
X % Specie	Liquidambar styracii es that are OBL, FACW, or		Gum,Sweet	owardin Classification:	FAC+		
		TAC (except TAC-). 40		Swaruin Classification.			
Remark	S						
	0.4.75019500						
Hydrolo	ogy	Prima	ary Wetland Hydrology Indicators	Secondary Hydrolog	y Indicators		
[]Red	orded Data (describe in re	marks) [] Inundated	[] Oxidized root	channels		
[Stream, Lake, or Tide C	Sage [] Saturated in upper 12 inches	[] Water-stained	leaves		
1	Aerial Photograph	Ī] Water marks	[] Local soil sun	ey data		
Ī	Other (describe in rema	rks) [1 Drift lines	[] FAC-Neutral t	est		
	# (60, 9) (2000) 2 (40) (1) (1) (1) (1) (2) (2) (1) (2) (2	33000000] Sediment deposits	[] Other (explain in remarks)			
Field O	bservations:	: -] Drainage patterns in wetlands	Librate dis Trimete d'Adaminader			
Ţ	Depth of Surface Water(in.)),	1 Brainage patterns in wedands				
1	Depth to Free Water in Pit(n.):					
1	Depth to Saturated Soils(in	.):					
Remar							
(E) 10/5	/drology observed.						
Soils							
Depth	Hor. Matrix	Mottle / 2nd Mottle		exture,			
<u>(in.)</u>	Color	Color Abu		tructure, etc.			
0-12	10YR 4/6		C	lay Loam			
NE SECT O	5 4 7 7 7						
2007-2000-2000	Soils Indicators						
	Histosol		[] Concretions				
VF 5.	Histic Epipedon		[] High Organic % in Sur				
I 1	Sulfidic Odor		[] Organic Streaking in Sandy Soils				
[] Probable Aquatic Moist Regime			[] Listed on Local Hydric Soils List				
[] Reducing Conditions			[] Listed on National Hydric Soils List				
[] Gleyed or Low-Chroma Colors			[] Other (explain in remarks)				
Linia Kin			T				
Unit Na			Taxonomy:				
Drainag	ge Class:		[] Field Observations match	map			
Remark	s						
Wetland	d Determination						
[False]	Hydrophytic Vegetation Pr	esent	[False] This Data Point is a	a Wetland			
	Hydric Soils Present	namen de	La mara a mara a mara a mara a				
New Section (Section)	Wetland Hydrology Preser	t					
170	() (E) (E) (E) (E) (E) (E) (E) (E) (E)	•					
Remark	5						



9.2 Agency Correspondence

The following appendix contains the correspondence between Georgia Transmission Corporation and appropriate federal and state agencies.

1. Correspondence with the Georgia Department of Natural Resources GNHP (Georgia Natural Heritage Program) regarding protected species occurrences.

Review of the reported information on the GNHP website (http://www.dnr.state.ga.us/dnr/wild/) indicates that there are no known locations of any listed or tracked species within the USGS quarter quadrangle that the project is within.

In addition to reviewing existing database information, the GNHP was to request information on all protected species and their known occurrences. A response from GNHP regarding this information was received August 2, 2005. GNHP reports a known occurrence of one aquatic species *Cyprinella xaenura* (Altamaha shiner) within a three mile radius of the south end of the proposed transmission line corridor.

2. The U.S. Fish and Wildlife Service (USFWS) website (http://athens.fws.gov) was used regarding the potential occurrence of protected species. The county index of Endangered Species provided the most current list of the county in which the project is located.

Noel Holcomb, Commissioner Dan Forster, Director

Georgia Department of Natural Resources Wildlife Resources Division

Nongame Conservation Section 2065 U.S. Highway 278, S.E., Social Circle, Georgia 30025-4743 (770) 918 6411

September 11, 2007

Kevin Mullinax Ecologist Jordan, Jones, & Goulding 6801 Governors Lake Parkway Building 200 Norcross, GA 30071

Subject:

Known Occurrences of Conservation Areas and Special Concern Animals and Plants On or Near Jim Moore Road - Sharon Church 230 kV Transmission Line Project, Barrow County, Georgia

Dear Mr. Mullinax:

This is in response to your request of August 8, 2007. According to our records, within a three-mile radius of the project corridor there are the following Natural Heritage Database occurrences:

Jim Moore Road Substation (-83.90664, 34.03491; NAD27):

Aesculus glabra (Ohio Buckeye) approx. 1.5 mi. NE of site
Alcovy River [High Priority Stream] approx. 2.0 mi. SW of site
Apalachee River [High Priority Stream] approx. 1.0 mi. SW of site
Little Mulberry River Park [Gwinnett County Parks and Recreation Department] approx.
0.5 mi. E of site

Gwinnett / Barrow County Line (-83.85428, 34.03837; NAD27):

Panax quinquefolius (American Ginseng) approx. 1.5 mi. NW of site

GA Veratrum woodii (Ozark Bunchflower) approx. 1.5 mi. NW of site

Sharon Church Substation (-83.80850, 34.09456; NAD27):

- US Amphianthus pusillus (Pool Sprite) approx. 2.5 mi. N of site
- GA Cyprinella xaenura (Altamaha Shiner) approx. 1.0 mi. NW of site in Duncan Creek Hemidactylium scutatum (Four-toed Salamander) approx. 2.0 mi. N of site
- US Isoetes melanospora (Black-spored Quillwort) approx. 2.5 mi. N of site
- US Isoetes tegetiformans (Mat-forming Quillwort) approx. 2.5 mi. N of site
- * Entries above proceeded by "US" indicates species with federal status in Georgia (Protected or Candidate). Species that are federally protected in Georgia are also state protected; "GA" indicates Georgia protected species.

Recommendations:

We have no records of species of concern within the project corridor. However, three federally listed species, *Amphianthus pusillus* (Pool Sprite), *Isoetes melanospora* (Black-spored Quillwort) and *Isoetes tegetiformans* (Mat-forming Quillwort) are within three miles of the proposed project. These species rely on granite rock outcrop habitats. If no outcrop habitats are found within the project corridor, this project should not negatively impact these species. We recommend thoroughly surveying the project corridor for these and other species of concern before any work is begun. Section 9 of the Endangered Species Act states that taking or harming of a listed species is prohibited. We recommend all requestors with projects located near federally protected species consult with Robin Goodloe of the United States Fish and Wildlife Service (706-613-9493, ext.221 or Robin_Goodloe@fws.gov).

In order to protect aquatic habitats and water quality, we recommend that all machinery be kept out of creeks during powerline construction. Streams should not be culverted/forded to allow equipment access during construction or for future ROW maintenance. Further, we strongly advocate retaining at least a 25-foot vegetative buffer between each stream bank and the closest power pole, and allow this buffer to regenerate to shrub-scrub growth after the pipe is installed (if the landowner is willing). We realize that some trees may have to be removed, but recommend that shrubs and ground vegetation be left in place. Wider buffers may be needed for projects where land slopes sharply toward the stream being crossed. We also recommend that stringent erosion control practices be used during construction activities and that vegetation is reestablished on disturbed areas as quickly as possible. Silt fences and other erosion control devices should be inspected and maintained until soil is stabilized by vegetation. Please use natural vegetation and grading techniques (e.g. vegetated swales, turn-offs, vegetated buffer strips) that will ensure that the project area does not serve as a conduit for storm water or pollutants into the water during or after construction. These measures will help protect water quality in the vicinity of the project as well as in downstream areas.

Please be aware that this project occurs near the Alcovy and Apalachee Rivers, both high priority streams. As part of an effort to develop a comprehensive wildlife conservation strategy for the state of Georgia, the Wildlife Resources division has developed and mapped a list of streams that are important to the protection or restoration of rare aquatic species and aquatic communities. High priority waters and their surrounding watersheds are a high priority for a broad array of conservation activities, but do not receive any additional legal protections. We now have GIS ESRI shapefiles of GA high priority waters available on our website (http://www.georgiawildlife.com/content/displaycontent.asp?txtDocument=89&txtPage=13). Please contact the Georgia Natural Heritage Program if you would like additional information on high priority waters.

New Data Available on the Nongame Conservation Section Website

We have recently updated the Nongame Conservation Section Website!!! You can view the updated rare species and natural community information by Quarter Quad, County and HUC8 Watershed. To access this information, please visit our GA Rare Species and Natural Community Information page at:

http://georgiawildlife.dnr.state.ga.us/content/displaycontent.asp?txtDocument=89

An updated ESRI shape file of our rare species and natural community data by quarter quad and county is also available. It can be downloaded from: http://georgiawildlife.dnr.state.ga.us/assets/documents/gnhp/gnhpds.zip

Disclaimer:

Please keep in mind the limitations of our database. The data collected by the Nongame Conservation Section comes from a variety of sources, including museum and herbarium records, literature, and reports from individuals and organizations, as well as field surveys by our staff biologists. In most cases the information is not the result of a recent on-site survey by our staff. Many areas of Georgia have never been surveyed thoroughly. Therefore, the Nongame Conservation Section can only occasionally provide definitive information on the presence or absence of rare species on a given site. Our files are updated constantly as new information is received. Thus, information provided by our program represents the existing data in our files at the time of the request and should not be considered a final statement on the species or area under consideration.

If you know of populations of special concern species that are not in our database, please fill out the appropriate data collection form and send it to our office. Forms can be obtained through our web site (http://www.georgiawildlife.com) or by contacting our office. If I can be of further assistance, please let me know.

Sincerely,

Katrina Morris

Thina Moris

Environmental Review Coordinator

9.3 Results of the Preliminary Environmental Justice Survey

Results of the Environmental Justice Survey Jim Moore Road-Sharon Church 230 kV Transmission Line

An environmental justice (EJ) survey was conducted for the Jim Moore Road-Sharon Church 230 kV Transmission Line in Barrow and Gwinnett Counties, Georgia. The survey was conducted in accordance with GTC's Environmental Justice Guidelines and Methodology for Analyzing Potential Environmental Justice Areas of Concern. The GTC EJ documents, based upon methodology developed by EPA Region IV, explain the fundamental details of this analysis. The EPA methodology is based on Census 1990; however, the minority and low-income population percentages in Georgia changed during the decade leading up to Census 2000. The minority population increased from approximately 30% in 1990 to 37.3% in 2000, while the low-income population decreased from 14.7% to 13.0%. The EPA has not yet developed new thresholds for the latest Census numbers. At this time, GTC is continuing to use the 1990 EPA thresholds for environmental justice evaluations. Therefore, the minority analysis is more inclusive than will be required by future EPA thresholds, but the low-income analysis is less inclusive. The results of the survey are detailed below.

Race: Minority populations were analyzed at the Census 2000 block level. The minority population was defined by grouping together all non-white races, Hispanics, and those whose race is described as the combination of two or more races. A block is considered to be a potential EJ area if the minority population percentage of the block is greater than the percentage specified as the EPA minority threshold (35.72% of the total population).

The proposed transmission line intersects 49 Census blocks (Figure 1). Ten blocks are in Gwinnett County, and 39 blocks are in Barrow County. Each entire intersecting block was evaluated for EJ purposes; however, the proposed transmission line follows along existing roadways for much of its length, and these roadways typically form the block boundaries. A single Census block along the proposed line in Barrow County has a minority population percentage above the EPA threshold and is therefore classified as a potential EJ area. Five (5) blocks along the proposed route have no population, and the remaining 43 blocks have minority population percentages that are below the EPA threshold and are not considered to be potential EJ areas. The single high-minority block is located along the south side of Union Grove Church Road, and the proposed transmission line is routed along the north side of the road.

A review of aerial photography indicates that numerous existing homes and businesses are found along the proposed route. The cross-country line segments generally pass through fields and forested areas and are sufficiently removed from existing structures. However, as the route approaches S.R. 324 (Auburn Road) from the east, two homes are located approximately 90 feet from the proposed line. Neither of these homes is in the high-minority Census block.


Income: Low-income populations were analyzed at the Census 2000 block group level. The low-income population was defined as those individuals living below the 1999 U.S. poverty levels. The block group is considered to be a potential EJ area if the low-income population percentage of a block group is greater than the percentage specified as the EPA low-income threshold (17.58% of the total population).


The proposed transmission line intersects a total of four (4) Census block group (Figure 2), two in each of the affected counties. Each entire intersecting block group was evaluated for EJ purposes, even though the proposed transmission line affects relatively small areas within the block groups. The low-income population percentages of these block groups range from 3.03% to 7.23% of the

Jim Moore Road-Sharon Church Transmission Line Environmental Justice Survey, February, 2008

total populations, all of which are well below the EPA threshold. Therefore, none of these block groups is considered to be a potential EJ area in terms of income.

Conclusion: The methodology utilized for this study is consistent with guidelines developed and advocated by EPA Region IV. The EPA guidelines are described fully in the GTC documents noted above. A review of the Jim Moore Road-Sharon Church 230 kV Transmission Line found a potential environmental justice area for minority populations but none for low-income populations. A review of aerial photography (March, 2003) was conducted as a component of this analysis. This review indicates that the proposed transmission line is primarily routed along existing roads which are relatively well-developed. Numerous homes and other structures are located along the proposed line, but the route does not directly impact any structures in potential EJ areas. Specific locations of minority or low-income populations cannot be determined at this level of analysis; however, the information available for use in this analysis indicates that construction of the proposed transmission line is not likely to result in disproportionately high and adverse impacts to minority or low-income populations.





9.4 Electrical Alternatives Analysis

Prepared by Georgia Transmission